


**Company:** MACPHERSON OIL COMPANY  
**Field:** ROUND MOUNTAIN  
**SEC 17** **TWN 28s** **RGE 29e** **API** **0403036583** **Well:** OLCESE 1 #A5i  
**Log Type:** WATER INJECTION PROFILE  
**Date:** 10-22-2009  
**Perfs:** 7" 1728-1788, 1792-1822  
**Co. Rate:** N/A  
**Top Press:** VACUUM  
**Csg Press:** 0 psi  
**Pick-Up:** 1865' **Fill:** 34' **F. L.:** 250'  
**Survey Rate:** 1250 B/D  
**TOP PERF & PACKER CHECK O.K.**  
**TUBING CHECKED O.K. @ 50' & PACKER.**  
**D.O.G.G.R. WITNESS DEAN KAHLER.**

# WATER INJECTION PROFILE



**Company:** MACPHERSON OIL COMPANY  
**Log Type:** WATER INJECTION PROFILE  
**Date:** 10-22-2009  
**Co. Rate:** N/A  
**Tbg Press:** VACUUM  
**Csg Press:** 0 psi  
**Pick-Up:** 1865' **Fill:** 34'  
**Survey Rate:** 1250 B/D  
**Field:** ROUND MOUNTAIN  
**SEC 17** **TWN 28s** **RGE 29e** **API 0403036583**  
**Well No:** OLCSE 1 #A 51  
**Perfs:** 7" 1728-1788, 1792-1822  
**Meas. Ref:** 13' D. F.  
**TOP PERF & PACKER CHECK O.K.**  
**TUBING CHECKED O.K. @ 50' & PACKER.**  
**D.O.G.G.R. WITNESS DEAN KAHLER.**


# MIGRATION CHECK

## TIME RECORDING

TOP PERF AND PACKER CHECK @ 1600'. INJECTED R/A SLUG OUT AND BY. WAITED 0 SECONDS, BEFORE STARTING LOGGING RUNS.

0 Sec.

## LOGGING RUNS



PACKER CHECK OK

TOP PERF CHECK OK

BACK GROUND

R.U.

VEDDR